


| | A | φB | Rc X |
|------|----|----|-------|
| 10SS | 35 | 35 | 3/8 |
| 15SS | 41 | 40 | 1/2 |
| 20SS | 45 | 50 | 3/4 |
| 25SS | 50 | 55 | 1 |
| 40SS | 70 | 70 | 1 1/2 |




SSバーナ

外 形 図

お問合せは TEL 03-5763-8711まで


タカミツ工業株式会社

| | A | φB | Rα |
|-------|----|------|-----|
| 6SSO | 30 | 10.5 | 1/8 |
| 8SSO | 35 | 13.8 | 1/4 |
| 10SSO | 40 | 17.3 | 3/8 |
| 15SSO | 60 | 21.7 | 1/2 |
| 20SSO | 65 | 27.2 | 3/4 |
| 25SSO | 75 | 34 | 1 |



SSOバーナ

外 形 図

お問い合わせは TEL 03-5763-8711まで

**トカミツ工業株式会社**